

8241 Premium High Hide Flat-

Wisconsin Homes White

hci product 8241 is a high quality <u>latex paint and primer in one</u> providing excellent coverage on interior surfaces and may be applied by roller, brush, or spray. This environmentally friendly paint provides excellent durability and is easy to touch up.

Wisconsin Homes White is specifically engineered by hci for exclusive use by Wisconsin Homes Inc.

During an industry standard scrub test (per ASTM D Resistance Tester), hci's Wisconsin Homes White retained its "no wear" status even after over 1,500 scrub cycles; comparatively a typical new construction product showed complete wear.



hci's Wisconsin Homes White is applied to the walls and ceiling in your new home, surrounding you with strength and durability that will last.



Custom Coatings for Industry

Premium High Hide Flat-Wisconsin Homes White

hci products number 8241 is a high quality latex paint and primer in one that provides excellent hide over new or previously painted interior surfaces and may be applied by roller, brush or spray. This environmentally friendly paint provides excellent durability and is easy to touch up.

CHARACTERISTICS

- Paint and Primer in one
- Excellent hide
- Excellent scrubbability
- Excellent touch up
- Environmentally friendly
- Use on interior walls and ceilings

Gloss - Flat
Weight Solids - 52.7% ± 2%
Volume Solids - 35.4 ± 2%
Viscosity - 98-103 KU
Spreading Rate - 568 Sq. Ft. per
gallon @ 1 dry mil.
(theoretical)
Specific Gravity - 1.38
VOC - 33 g/L
VOC (less water) - 85.5 g/L

Dry Time - (77°F at 50% R.H.)
To Touch - 1 hour
To Recoat - 4 hours

*Dry times may vary depending on temperature, humidity and degree of air movement

SPECIFICATIONS

New or previously painted drywall Previously coated surfaces Commercial & Residential Apartment complexes Modular homes

APPLICATION

EQUIPMENT: This product can be applied by brush, roll, conventional air, or airless.

REDUCTION: No reduction is necessary. This product is made ready to apply. If reduction is needed due to application conditions, use water at no more than 5% by volume.

CLEANUP INFORMATION

Clean equipment with soap and water.

SURFACE PREPARATION

Surfaces must be dry and free from all dust, dirt, oil, or other contaminates. Scrape or sand all loose or peeling paint. Prime the surface with recommended primer.

WARNING! Removal of old paint by sanding, scraping or other means may generate dust or fumes that contain lead. Exposure to lead dust or fumes may cause brain damage or other adverse health effects, especially in children or pregnant women. Controlling exposure to lead or other hazardous substances requires the use of proper protective equipment, such as a properly fitted respirator (NIOSH approved) and proper containment and cleanup. For more information, call the National Lead Information Center at 1-800-424-LEAD (In US) or contact your local health authority

CAUTIONS

See SDS for specific precautions.

At hci, it is our goal to create and customize products that fit each customer's specific needs. We pledge to provide efficiency and value, and be environmentally responsible. Please contact an hci representative for more information. 1-800-433-6331